



Vehicle History Report™

2021 MERCEDES-BENZ G-CLASS AMG G 63

VIN: W1NYC7HJ3MX410085
4 DOOR WAGON/SPORT
UTILITY
4.0L V8
GASOLINE
ALL WHEEL DRIVE



No accidents or damage reported to CARFAX



At least 1 open recall



CARFAX 1-Owner vehicle



Commercial vehicle



Last owned in Pennsylvania



48 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/27/23 at 2:58:36 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

Owner 1

Year purchased

2022

Type of owner

Commercial

Estimated length of ownership



2 months

Owned in the following states/provinces

Pennsylvania

Estimated miles driven per year

Last reported odometer reading

48



Title History

CARFAX guarantees the information in this section

Owner 1

Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



Guaranteed
No Problem

Odometer Brands


Not Actual Mileage | Exceeds Mechanical Limits





Guaranteed
No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
View Terms | View Certificate

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.	Recall Reported
Basic Warranty Original warranty estimated to have 30 months or 49,952 miles remaining. Confirm with dealer or vehicle manufacturer.	<input checked="" type="checkbox"/> Warranty Active

 Detailed History			
 Owner 1 Purchased: 2022			Commercial Vehicle
Date	Mileage	Source	Comments
04/04/2022	48	Pennsylvania Motor Vehicle Dept. Philadelphia, PA Title #8451895501 T	Title issued or updated - First owner reported - Titled or registered as commercial vehicle
06/06/2022		Rolls-Royce of Long Island Plainview, NY 847-782-0300	Vehicle offered for sale
04/05/2023		Mercedes-Benz USA LLC	Manufacturer Safety recall issued - NHTSA #23V097 - Recall #2023030005 Recall - Safety Title/ Topic: Check Front Axle Wiring

Harness MY: 2019-2021 Model(s): G-Class,XX-Cla
-Status: Remedy Available

Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall

⊖ [Learn more about this recall](#)

Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2019-2022 G-Class (463 platform) vehicles, the front axle wiring harness might contact an auxiliary oil cooler. In this case, the wiring harness might contact an auxiliary oil cooler and chafe, which could potentially damage the wiring harness over time. As a result, impairment of ABS and ESP functionality cannot be ruled out, which could potentially increase the risk of a crash. An authorized Mercedes-Benz dealership, will inspect the front axle wiring harness on the affected vehicles and replace it, if necessary. After inspection a protective sleeve will be installed, if the wiring harness is not replaced.

In this case, the wiring harness might contact an auxiliary oil cooler and chafe, which could potentially damage the wiring harness over time. As a result, impairment of ABS and ESP functionality cannot be ruled out, which could potentially increase the risk of a crash.

Remedy: An authorized Mercedes-Benz dealership, will inspect the front axle wiring harness on the affected vehicles and replace it, if necessary. After inspection a protective sleeve will be installed, if the wiring harness is not replaced.

06/26/2023

Mercedes-Benz USA LLC

Manufacturer Safety recall issued

- NHTSA #23V445

- Recall #2023060010 23P2197608

-Status: Remedy Not Yet Available

Click here or call 1-800-367-6372 to locate an authorized Mercedes-Benz dealer near you to obtain more information about this recall

⊖ [Learn more about this recall](#)

Description: Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2021-2023 GLE/GLS (167 platform), C-Class (205, 206 platform), E-Class (213 platform), S-Class (223 platform), SL (232 platform), E-Class Coupe/Convertible (238 platform), GLC (253 platform), CLS (257 platform), AMG GT 4-doors Coupe (290 platform) and G-Class (463 platform) vehicles, the fuel pump impeller might not meet current specifications in regards to material characteristics. As a consequence, the impeller might deform and therefore come into contact with the fuel pump housing, leading to a mechanical resistance. In some instances, this could lead to a shutdown of the fuel pump. As a result, the vehicle could lose propulsion, which could increase the risk of crash or injury. An authorized Mercedes-Benz dealership will replace the fuel delivery module on the affected vehicles.

As a consequence, the impeller might deform and therefore come into contact with the fuel pump housing, leading to a mechanical resistance. In some instances, this could lead to a shutdown of the fuel pump. As a result, the vehicle could lose propulsion, which could increase the risk of crash or injury.

Remedy: An authorized Mercedes-Benz dealership will replace the fuel delivery module on the affected vehicles.

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

Commercial

Vehicle was registered for business purposes.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.
10/27/23 2:58:36 PM (CDT)

