
CARFAX Report

1990 Mercedes-Benz 190-Class 190 E 2.6

152,946 mi | **VIN:** WDBDA29D9LF678052

Sedan 4 DR | 2.6L I6 F | Gasoline | Rear wheel drive



NO ACCIDENTS REPORTED

No Accidents or Damage Reported to CARFAX

20 Service History Records

46 Detailed Records Available

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/10/26 at 10:08:12 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Recent Service Highlights

Key services performed in the last 12 months

Service	Comments	Date
Oil	Oil and filter changed	01/07/2026



This car has been recently serviced. That's a good thing!

CARFAX Additional History

Not all accidents / issues are reported to CARFAX

	Summary
Total Loss No total loss reported to CARFAX.	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported
Manufacturer Recall No open recalls reported to CARFAX.	No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	**Warranty Expired**

CARFAX Title History	Summary
Damage Brands Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon	No Problem
Odometer Brands Not Actual Mileage | Exceeds Mechanical Limits	No Problem

CARFAX Detailed History

Date	Mileage	Source	Comments
12/05/1992	13,961	California Inspection Station Yorba Linda, CA	**Passed emissions inspection**
11/18/1994	24,139	California Inspection Station Yorba Linda, CA	**Passed emissions inspection**
11/18/1996	36,296	California Inspection Station Yorba Linda, CA	**Passed emissions inspection**
12/01/1998	47,644	California Inspection Station	**Passed emissions inspection**
12/22/1999		California Motor Vehicle Dept. Irvine, CA	**Title issued or updated**
11/15/2000	58,204	California Inspection Station San Bernardino, CA	**Passed emissions inspection**
10/30/2002	67,113	California Inspection Station Rowland Heights, CA	**Passed emissions inspection**
10/14/2003	72,414	Service Facility	**Vehicle serviced**
12/06/2004	76,155	California Inspection Station Rowland Heights, CA	**Passed emissions inspection**
05/19/2006		Fletcher Jones Motorcars Newport Beach, CA 949-718-3000 **4.6 / 5.0** 725 Verified Reviews **490** Customer Favorites	**Vehicle serviced** - A/C and heating system checked - Blower motor switch replaced - Driveshaft flex disc replaced - Oil and filter changed - Vehicle washed/detailed
11/29/2006	80,184	California Inspection Station Rowland Heights, CA	**Passed emissions inspection**
12/02/2008	83,851	California Inspection Station Rowland Heights, CA	**Passed emissions inspection**
10/22/2009		Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 **5.0 / 5.0** 61 Verified Reviews **16** Customer Favorites	**Vehicle serviced**
04/22/2010	86,073	Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507	**Vehicle serviced** - Maintenance inspection completed - Air filter replaced

		★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		- Battery/charging system checked - Front strut(s) replaced - Lights checked - Oil and filter changed - Tire condition and pressure checked
05/19/2010	86,287	Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 ★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		**Vehicle serviced**
12/07/2010	88,026	California Inspection Station Irvine, CA		**Passed emissions inspection**
01/04/2011	88,353	Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 ★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		**Vehicle serviced**
09/09/2011	90,441	Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 ★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		**Vehicle serviced** - Maintenance inspection completed - Air filter replaced - Battery/charging system checked - Lights checked - Oil and filter changed - Rear brake rotor(s) replaced - Tire condition and pressure checked
03/29/2012	91,440	Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 ★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		**Vehicle serviced**
10/26/2012	92,451	California Inspection Station Irvine, CA		**Passed emissions inspection**
02/04/2013	92,961	Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 ★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		**Vehicle serviced**
07/11/2013	93,399	Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 ★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		**Vehicle serviced**
09/26/2013	93,402	Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 ★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		**Vehicle serviced**
11/19/2014	93,406	California Inspection Station Irvine, CA		**Passed emissions inspection**
03/28/2016		Coast MBZ/BMW Service Costa Mesa, CA 714-957-1507 ★ **5.0 / 5.0** 61 Verified Reviews ♥ **16** Customer Favorites		**Vehicle serviced** - Ignition coil(s) replaced

02/07/2017	93,691	California Inspection Station San Diego, CA		**Passed emissions inspection**
02/08/2017		California Motor Vehicle Dept. Escondido, CA		**Title issued or updated** - New owner reported - Correction to record
04/17/2017		California Motor Vehicle Dept. San Diego, CA		**Title issued or updated** - New owner reported
09/11/2017	96,994	Mercedes-Benz of Escondido Escondido, CA 760-233-5160 **4.4 / 5.0** 1,023 Verified Reviews **6,949** Customer Favorites		**Vehicle serviced** - Vehicle washed/detailed
11/24/2018	109,377	California Inspection Station Escondido, CA		**Passed emissions inspection**
02/04/2019	110,995	Mercedes-Benz of Escondido Escondido, CA 760-745-5000 **4.4 / 5.0** 1,023 Verified Reviews **6,949** Customer Favorites		**Vehicle serviced** - Lower control arm(s) replaced - Tire condition and pressure checked - Vehicle washed/detailed
05/17/2019	114,017	Mercedes-Benz of Escondido Escondido, CA 760-745-5000 **4.4 / 5.0** 1,023 Verified Reviews **6,949** Customer Favorites		**Vehicle serviced** - Maintenance inspection completed - Tire condition and pressure checked
11/17/2020	132,442	California Inspection Station Escondido, CA		**Passed emissions inspection**
11/16/2022	138,311	California Inspection Station Escondido, CA		**Passed emissions inspection**
02/21/2024	145,477	American Tire Depot San Diego, CA 858-278-6200 **4.3 / 5.0** 52 Verified Reviews **1** Customer Favorite		**Vehicle serviced** - Alignment performed
10/10/2024	149,490	California Inspection Station Escondido, CA		**Failed emissions inspection** - **Designated GROSS POLLUTER**
10/10/2024	149,551	California Inspection Station Escondido, CA		**Passed emissions inspection**
10/11/2024		Virginia Motor Vehicle Dept.		**Vehicle purchase reported**
10/24/2024		Virginia Inspection Station		**Passed safety inspection**
10/24/2024	149,579	Virginia Motor Vehicle Dept. Falls Church, VA		**Title or registration issued** - New owner reported
11/27/2024	149,910	Craftmans Auto Care - Ashburn Ashburn, VA 571-564-2070 **4.8 / 5.0** 186 Verified Reviews		**Vehicle serviced** - Engine/powertrain computer/module checked - Oxygen sensor replaced

		60 Customer Favorites		
10/06/2025	151,971	Mercedes-Benz of Arlington Arlington, VA 703-525-2100 **4.7 / 5.0** 1,957 Verified Reviews **1,015** Customer Favorites		**Vehicle serviced** - Maintenance inspection completed - Vehicle washed/detailed
10/24/2025	152,074	Virginia Inspection Station		**Passed safety inspection**
01/07/2026	152,669	Mercedes-Benz of Arlington Arlington, VA 703-525-2100 **4.7 / 5.0** 1,957 Verified Reviews **1,015** Customer Favorites		**Vehicle serviced** - Maintenance inspection completed - Fuel filler cap secured - Lug nut(s)/bolt(s) replaced - Oil and filter changed - Serpentine belt replaced - Wheel bearing(s) serviced - Vehicle washed/detailed
05/26/2026	152,799	Ben Nielsen's Skyline Automotive Falls Church, VA 703-845-8477 **4.8 / 5.0** 222 Verified Reviews **49** Customer Favorites		**Vehicle serviced** - Maintenance inspection completed - Battery replaced
10/08/2026	152,946	Virginia Inspection Station		**Passed safety inspection**

Have Questions? Please visit our Help Center at www.carfax.com.

CARFAX Glossary

Failed Emissions Inspection
The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

Gross Polluter
A Gross Polluter is a vehicle that fails an emissions inspection with below-standard scores. These vehicles can pollute as much as 18 times more than a vehicle that passes an emissions inspection. It is illegal to drive or sell a gross polluting vehicle in California, and it cannot be registered with the DMV. CARFAX recommends checking the latest Vehicle Inspection Report to confirm the proper repairs have been completed before purchasing.

New Owner Reported
When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History
CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued
A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: facebook.com/CARFAX @CARFAXinc About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2026 CARFAX, Inc., part of Mobility Global. All rights reserved.
11/10/26 10:08:12 AM (CST)

SHOW ME THE CARFAX