



# Vehicle History Report™

## 1989 MERCEDES-BENZ 300-CLASS 300 SE

VIN: WDBCA24D3KA463457  
SEDAN 4 DR  
3.0L I6 F  
GASOLINE  
REAR WHEEL DRIVE



No accidents or damage reported to CARFAX



12 Service history records



26 Detailed records available



110,135 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 7/17/23 at 7:07:49 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



## Title History

CARFAX guarantees the information in this section

### Summary

#### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon



**Guaranteed**  
No Problem

#### Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits



**Guaranteed**  
No Problem



**GUARANTEED** - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.  
[View Terms](#) | [View Certificate](#)



## Additional History

Not all accidents / issues are reported to CARFAX

### Summary

#### Total Loss

No total loss reported to CARFAX.



No Issues  
Reported

#### Structural Damage

No structural damage reported to CARFAX.



No Issues  
Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.



No Issues  
Reported

#### Odometer Check

No indication of an odometer rollback.



No Issues  
Indicated

#### Accident / Damage



No accidents or damage reported to CARFAX.













No Issues  
Reported

<b>Manufacturer Recall</b> Check with an authorized Mercedes-Benz dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> No data reported to CARFAX.	No Data Reported

**CARFAX** Detailed History

Date	Mileage	Source	Comments
04/13/1991	14,932	California Inspection Station Palmdale, CA	<b>Passed emissions inspection</b>
04/03/1993	26,822	California Inspection Station Palmdale, CA	<b>Passed emissions inspection</b>
03/28/1997	52,974	California Inspection Station Palmdale, CA	<b>Passed emissions inspection</b>
04/05/1999	67,287	California Inspection Station Temecula, CA	<b>Passed emissions inspection</b>
04/28/1999		California Motor Vehicle Dept. Lake Arrowhead, CA	<b>Title issued or updated</b>
08/30/1999	71,375	Service Facility	 <b>Vehicle serviced</b> - Recommended maintenance performed - Oil and filter changed - Rear brake pads replaced - Front brake rotor(s) replaced - Front brake pads replaced - Headlight bulb(s) replaced - Light bulb(s) replaced
10/20/2000	84,538	Service Facility	 <b>Vehicle serviced</b> - Recommended maintenance performed - Fuel pump replaced - Voltage regulator replaced - Water pump replaced - Thermostat replaced - Steering damper replaced - Four wheel alignment performed - Front brake pads replaced - Vehicle washed/detailed - Oil and filter changed

09/27/2002	87,270	California Inspection Station Twin Peaks, CA		<b>Failed emissions inspection</b>
09/27/2002		Vehicle Repair Center		<b>Vehicle serviced</b> - Fuel cap repaired
09/27/2002		California Inspection Station Twin Peaks, CA		<b>Passed emissions inspection</b>
04/09/2004	94,241	California Inspection Station Twin Peaks, CA		<b>Passed emissions inspection</b>
12/02/2020		California Motor Vehicle Dept. Hemet, CA		<b>Title issued or updated</b> - Registration updated when owner moved the vehicle to a new location
12/14/2020	97,633	Integrity Tire Hemet, CA 951-658-3145 ★ 4.6 / 5.0 82 Verified Reviews ❤️ 70 Customer Favorites		<b>Vehicle serviced</b> - Alignment checked
12/23/2020	97,853	California Inspection Station Hemet, CA		<b>Passed emissions inspection</b>
01/24/2021	98,986	Integrity Tire Hemet, CA 951-658-3145 ★ 4.6 / 5.0 82 Verified Reviews ❤️ 70 Customer Favorites		<b>Vehicle serviced</b>
10/05/2021	103,331	Excellent Auto Care & Tire Temecula, CA 951-699-1009 ★ 4.8 / 5.0 161 Verified Reviews ❤️ 159 Customer Favorites		<b>Vehicle serviced</b> - Oil and filter changed
01/16/2022	105,349	Excellent Auto Care & Tire Temecula, CA 951-699-1009 ★ 4.8 / 5.0 161 Verified Reviews ❤️ 159 Customer Favorites		<b>Vehicle serviced</b> - Oil and filter changed

02/08/2022	106,035	Excellent Auto Care & Tire Temecula, CA 951-699-1009 ★ 4.8 / 5.0 161 Verified Reviews ♥ 159 Customer Favorites		<b>Vehicle serviced</b> - Emissions inspection performed
02/08/2022		California Inspection Station Temecula, CA		<b>Passed emissions inspection</b>
11/09/2022	108,468	Midas Temecula, CA 951-308-9114 ★ 4.9 / 5.0 74 Verified Reviews ♥ 54 Customer Favorites		<b>Vehicle serviced</b> - Brakes checked
12/12/2022	109,223	Excellent Auto Care & Tire Temecula, CA 951-699-1009 ★ 4.8 / 5.0 161 Verified Reviews ♥ 159 Customer Favorites		<b>Vehicle serviced</b> - Emissions inspection performed
12/12/2022		California Inspection Station Temecula, CA		<b>Passed emissions inspection</b>
12/15/2022		California Motor Vehicle Dept. Anaheim, CA		<b>Title issued or updated</b> - New owner reported
01/29/2023	109,224	Excellent Auto Care & Tire Temecula, CA 951-699-1009 ★ 4.8 / 5.0 161 Verified Reviews ♥ 159 Customer Favorites		<b>Vehicle serviced</b> - Serpentine belt replaced
02/26/2023	109,225	Excellent Auto Care & Tire Temecula, CA 951-699-1009 ★ 4.8 / 5.0 161 Verified Reviews ♥ 159 Customer Favorites		<b>Vehicle serviced</b> - Front axle(s) replaced/repared
04/17/2023	110,135	California Inspection Station Downey, CA		<b>Passed emissions inspection</b>

Have Questions? Please visit our Help Center at [www.carfax.com](http://www.carfax.com).



## Glossary

### **Failed Emissions Inspection**

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

### **New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

### **Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### **Title Issued**

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.  
7/17/23 7:07:49 PM (CDT)

